

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
2961 E. COLORADO ST., PASADENA, CALIF.

No. 11347

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080030-0


RECEIVED FROM

PLANT #9

DATE REC'D. 2-25-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. S.O. NO.			
	322	NOTED	50	0	10								
DRAWING NO. AND DESCRIPTION										QUANTITY		REMARKS	
										ACCEPTED	REJECTED		
9	731832 Bolt										9		
IPS #A003302													
													

RECEIVED BY *Barcelos* INSPECTED BY *Qua* DATE 2/28/57

REJECTS RETURNED ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11348


RECEIVED FROM

PLANT #9

DATE REC'D. 2-25-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO. S.O. NO.			
	322	NOTED	6	0	10								
DRAWING NO. AND DESCRIPTION										QUANTITY		REMARKS	
										ACCEPTED	REJECTED		
130	731374 Washer										130		
IPS #A003292													
													

RECEIVED BY *Barcelos* INSPECTED BY *Qua* DATE 2/25/57

ON SHIP. MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080030-0